

Quick Workstation Set Up:

1. Identify and verify all components are present as described on equipment list
2. Prepare mini PC for installation:
 - a. Plug power cord into mini PC



3. Connect power cords and display port cables into monitors, plug display port cables into back of mini PC.



4. Connect power cords into power strip:

5. Follow instructions included with mouse and keyboard:
6. Turn on mini PC:

